

Fig. 1a




Fig. 1b




Fig. 2a




Fig. 2b




Fig. 3a




Fig. 3b




Fig. 3c




Fig. 3d

003121-57204650




Fig. 3e




Fig. 3f




Fig. 3g




Fig. 4




Fig. 5a




Fig. 5b




Fig. 6




Fig. 7a




Fig. 7b

Fig. 8a






Fig. 8b



Segmenting Diagram

FIG. 8c



Perforating between Segments





Fig. 9




[illegible]

FIG. 10A




FIG. 10B




Fig. 11




FIG. 12

